

December 4, 2018

Robert Welch Project Manager City of Beverly Hills 345 Foothill Road Beverly Hills, CA 90210

Daniel Comorre Sr. Director, Construction Management Los Angeles County Metropolitan Transportation Authority One Gateway Plaza, 17th Floor Los Angeles, CA 90012

Subject: Segment 2 - Purple Line Extension Project ICM Weekly Report

(November 25, 2018 – December 1, 2018)

Dear Mr. Welch and Mr. Comorre:

Environmental Intelligence, LLC (EI) has been retained by the City of Beverly Hills (COBH) and the Los Angeles County Metropolitan Transportation Authority (Metro) to serve as the independent compliance monitor (ICM) during construction of the Purple Line Extension Project. Monitoring is required to ensure that construction is in compliance with (1) the Memorandum of Agreement (MOA) for Southern California Edison's (SCE's) Advance Utilities Relocation Phase of the Purple Line Extension Project – Segment 2 – Between the City of Beverly Hills and the Los Angeles Metropolitan Transportation Authority (City Agreement No. 384-17), (2) the MOA for the Third Party Advance Utility Relocation Phase of the Purple Line Extension Project – Section 2 - Between the City of Beverly Hills and the Los Angeles Metropolitan Transportation Authority (City Agreement No. 648-17) and (3) the Agreement titled "Demolition and Public Right-of-Way Use Permit for the Los Angeles County Metropolitan Transportation Authority and its Contractor to Clear All Buildings and Existing Improvements at 9430 Wilshire Boulevard, Install Noise Monitoring Equipment and Sound Walls for Future Construction and a Laydown Area for the Wilshire/Rodeo Station of Section Two of the Purple Line Extension Project" (Agreement dated June 5th, 2018). The following information summarizes the ICM monitoring activities that occurred at the Segment 2 site (Rodeo Station site) during the week of November 25, 2018 – December 1, 2018. Construction activities were not conducted on November 25, November 29, or December 1.

Construction activities during the week included Ace Gallery demolition focused on the foundation, west wall, and west columns; sorting and processing demolition debris; as well as hauling demolition debris offsite. EI ICMs were present on site during all construction activities and conducted routine noise measurements at selected noise monitoring locations as well as compliance checks in accordance with the MOAs and associated attachments, exhibits, traffic closure notifications, and traffic management plans. At the conclusion of each work shift, daily monitoring reports were prepared by each ICM. Attachment B (Daily Monitoring Report Summaries) provides detailed daily monitoring reports and photographs of construction activities.

VIOLATION SUMMARY

During the week, EI ICMs identified one (1) violation during construction activities. Table I provides a summary of the violation identified during the week of November 25, 2018 – December 1, 2018 and Exhibit 1 (*Violation Location [November 25 – December 1, 2018]*) provides a location map depicting the reported

Robert Welch Daniel Comorre December 4, 2018

violation. Violation details are included as Attachment A (*Violations*). Daily monitoring reports and photographs of construction activities are provided as Attachment B (*Daily Monitoring Report Summaries*). Daily noise monitoring data are provided in Attachment C (*Noise Monitoring Data Log*).

CONCLUSION

To date, 44 violations have been issued, four (4) of which have been rescinded since the beginning of construction of the Purple Line Extension Project – Segment 2. Project construction activities are ongoing and EI ICMs continue to monitor all construction activities applicable to the MOA on a daily basis.

If you have any questions or comments regarding this letter, please contact me directly at 310.469.8989 or jeremiahgeorge@enviro-intel.com.

Sincerely,

ENVIRONMENTAL INTELLIGENCE, LLC

Jeremiah George Project Manager

Attachments: Attachment A: Violations

Attachment B: Daily Monitoring Report Summaries

Attachment C: Noise Monitoring Data Log

cc: Valerie Mudegoren, City of Beverly Hills

Alexander Cantwell, Los Angeles County Metropolitan Transportation Authority Anna Noyola, Los Angeles County Metropolitan Transportation Authority Kimberly Wilson, Los Angeles County Metropolitan Transportation Authority David Cooper, Los Angeles County Metropolitan Transportation Authority Namrata Cariapa, Los Angeles County Metropolitan Transportation Authority Stacy Sinclair, Los Angeles County Metropolitan Transportation Authority Hank Scheetz, Los Angeles County Metropolitan Transportation Authority

Brett Barnett, Psomas Bill Zein, Psomas

Farzad Vakilitabar, Psomas Alex Kay, City of Beverly Hills



TABLE I: VIOLATION SUMMARY (NOVEMBER 25, 2018 – DECEMBER 1, 2018)

Violation ID	Date	Time	ICM	Location	Condition Violated	Iteration - Violation	Metro Response
44	11/26/2018	14:23	Jorge Guzman	125 S. Reeves Dr. 90212	Demolition Permit Conditions 17, 18, and "Noise Monitoring" Section 4.6	1 - Warning	






EXHIBIT 1: VIOLATION LOCATION (NOVEMBER 25 - DECEMBER 1, 2018)



Attachment A - Violations



UID:1154 Date:11/26/2018 ICM Violation Form - Section 2 AUR MOA 648-17

Violation Details

1. Violation ID

2. Violation Iteration 1 - Warning3. Time of Violation 14:23

4. Address 125 S. Reeves Dr. 90212

Applicable Measures

5. Memorandum of Agreement No. 648-17

6. Exhibit A: Third Party Utility Permit and City of Beverly Hills Conditions for Approval

7. Exhibit D: Metro 5-Step Noise Control Plan for Advanced Utility Work in Beverly Hills

8. Other Plans

9. Other Plan Description

• Ace Gallery Permit Conditions 17, 18, and "Noise Monitoring" section 4.6



Latitude: 34.066137 **Longitude:** -118.398245

Elevation: - - -

Notes

Violation ID: 44

At 14:23 hours, the ICM Jorge Guzman started a noise measurement at RD-5. During the measurement, work consisted of a Silverado Contractor excavator with breaker attachment and Silverado Contractors skid steer with breaker attachment breaking concrete inside the Ace Gallery. This project-related activity produced a noise reading of 66.3 LAeq (15-minute). The threshold at this receptor at this time of day is 65 LAeq (15-minute). The excessive noise is a violation of Ace Gallery Demolition Permit Conditions 17, 18, and "Noise Monitoring" section 4.6. The ICM notified Metro Inspector Luis Garcia of the violation. This is the first incidence of this violation at this location within the last ten days.





Attachment B

Daily Monitoring Reports 11/25/2018 - 12/01/2018



Summaries (5)

Date Monday, November 26, 2018

Monitor Jorge Guzman

Location Rodeo

Time 08:00:00 to 15:45:00

Compliant

Summary

Contractors/Subcontractors: TPOG; Silverado Contractors; VAI

Representatives On-Site: Miguel Ballesteros (Silverado Contractors); Luis Garcia (Metro); Robert Renteria (Metro); Phil Lattuca (Psomas)

Work Location(s): Ace Gallery at 9430 Wilshire Blvd;

The ICM was in possession of applicable COBH-approved closure notifications, TCP for the day's work, and the Ace Gallery Demolition Permit on November 26th, 2018. El ICM Jorge Guzman met with Silverado Contractors Superintendent Miguel Ballesteros and Metro Inspector Luis Garcia to discuss the day's activities. At the beginning of the shift, the ICM calibrated the sound meter at 94.00 dB.

Work for the day included jackhammering columns along the remaining west wall of the Ace Gallery, jackhammering the foundation of the Ace Gallery main structure, and sorting and processing debris.

At 14:23 hours, the ICM Jorge Guzman started a noise measurement at RD-5. During the measurement, work consisted of a Silverado Contractor excavator (with breaker attachment) and skid steer (with breaker attachment) breaking concrete inside the Ace Gallery. This project-related activity produced a noise reading of 66.3 LAeq (15-minute). The threshold at this receptor at this time of day is 65 LAeq (15-minute). The excessive noise is a violation of Ace Gallery Demolition Permit Conditions 17, 18 and "Noise Monitoring" section 4.6. The ICM notified Metro Inspector Luis Garcia of the violation. This is the first incidence of this violation at this location within the last ten days.

Tuesday, November 27, 2018 Date

Monitor **Daniel Chang**

Location Rodeo

08:00:00 to 16:30:00 Time

Compliant

Contractors/Subcontractors: TPOG; Silverado Contractors; Morgner Summary

Representatives On-Site: Miguel Ballesteros (Silverado Contractors); Luis Garcia (Metro); David Ramirez (Psomas); Phil Lattuca (Psomas); Alex

Kay (COBH)

Work Location(s): Ace Gallery at 9430 Wilshire Blvd.

The ICM was in possession of applicable COBH-approved closure notifications, TCP for the day's work, and the Ace Gallery Demolition Permit on November 27th, 2018. EI ICM Daniel Chang met with Metro Inspector Luis Garcia to discuss the day's activities. At the beginning of the shift, the ICM calibrated the sound meter at 93.9 dB (to 94.00 dB).

Work for the day included Ace Gallery demolition focused on the foundation and west wall, removal of the Ace Gallery foundation, hauling demolition debris off-site, as well as moving debris and organizing the site.





Attachment B

Daily Monitoring Reports 11/25/2018 - 12/01/2018



Date Wednesday, November 28, 2018

Monitor Annamarie Hand

Location Rodeo

Time 07:45:00 to 16:30:00

Compliant Yes

Summary Contractors/Subcontractors: TPOG; Silverado Contractors; SSI; Morgner

Representatives On-Site: Miguel Ballesteros (Silverado Contractors); Luis Garcia (Metro); Robert Renteria (Metro); Phil Lattuca (Psomas); Marcus

Zamora (Morgner)

Work Location(s): Ace Gallery at 9430 Wilshire Blvd.

The ICM was in possession of applicable COBH-approved closure notifications, TCP for the day's work, and the Ace Gallery Demolition Permit on November 28th, 2018. EI ICM Annamarie Hand met with Silverado Contractors Superintendent Miguel Ballesteros to discuss the day's activities.

At the beginning of the shift, the ICM calibrated the sound meter at 94.00 dB.

Work for the day included processing debris in the Ace Gallery yard, water-proofing the west wall, and hauling demolition debris off-site.

Date Thursday, November 29, 2018

Monitor Daniel Chang

Location Rodeo

Time 08:00:00 to 12:00:00

Compliant N/A

Summary Contractors/Subcontractors: N/A

Representatives On-Site: N/A

Work Location(s): N/A

The ICM was in possession of applicable COBH-approved closure notifications, TCP for the day's work, and the Ace Gallery Demolition Permit on November 29th, 2018. EI ICM Daniel Chang spoke with Metro Inspector Luis Garcia to discuss the day's activities, and Mr. Garcia stated that the Ace Gallery work for the day was cancelled because of the rain. At the beginning of the shift, the ICM calibrated the sound meter at 94.00 dB.

Scheduled work activities did not occur as planned, and the ICM left the site at 12:00 hours.

4 hour minimum for setup.

Date Friday, November 30, 2018

Monitor Daniel Chang

Location Rodeo

Time 08:00:00 to 16:30:00

Compliant Yes

Summary Contractors/Subcontractors: TPOG; Silverado Contractors

Representatives On-Site: Miguel Ballesteros (Silverado Contractors); Luis Garcia (Metro); Phil Lattuca (Psomas)

Work Location(s): Ace Gallery at 9430 Wilshire Blvd.

The ICM was in possession of applicable COBH-approved closure notifications, TCP for the day's work, and the Ace Gallery Demolition Permit on November 30th, 2018. El ICM Daniel Chang met with Metro Inspector Luis Garcia to discuss the day's activities. At the beginning of the shift, the

ICM calibrated the sound meter at 93.9 dB (to 94.00 dB).

Work for the day included breaking down material, removing the Ace Gallery foundation, and transporting the man-lift off-site.





Photos



Photos (17)

 UID:
 1152
 Latitude:
 34.06647

 Date:
 Nov 26, 2018
 Longitude:
 -118.39826

 Type:
 Construction Activity
 Elevation:
 --

Notes

Photo shows Silverado Contractors crew utilizing breaker attachment on skid steer and hand-held chipping gun to clear columns of concrete and expose steel beams.



 UID:
 1153
 Latitude:
 34.06641

 Date:
 Nov 26, 2018
 Longitude:
 -118.39814

 Type:
 Construction Activity
 Elevation:
 --

Notes

Photo shows Silverado Contractors excavator with breaker attachment working on demolition of Ace Gallery main structure foundation.



 UID:
 1150
 Latitude:
 34.06689

 Date:
 Nov 26, 2018
 Longitude:
 -118.39829

 Type:
 Construction Activity
 Elevation:
 --

Notes

Photo shows VAI flat bed truck exiting Ace Gallery site eastbound on Wilshire Blvd.



 UID:
 1151
 Latitude:
 34.06641

 Date:
 Nov 26, 2018
 Longitude:
 -118.39826

 Type:
 Construction Activity
 Elevation:
 --

Notes

Photo shows Silverado Contractors excavator loading bin with debris.



 UID:
 1156
 Latitude:
 34.066906

 Date:
 Nov 27, 2018
 Longitude:
 -118.3983

 Type:
 Construction Activity
 Elevation:
 --

Notes

 $\label{lem:contractors} \mbox{ Photo shows Silverado Contractors loading haul trucks with demolition debris.}$







Photos



 UID:
 1157
 Latitude:
 34.066887

 Date:
 Nov 27, 2018
 Longitude:
 -118.398354

 Type:
 Construction Activity
 Elevation:
 --

Notes

Photo shows Silverado Contractors removing the Ace Gallery foundation and moving debris.



 UID:
 1155
 Latitude:
 34.066929

 Date:
 Nov 27, 2018
 Longitude:
 -118.398331

 Type:
 Construction Activity
 Elevation:
 --

Notes

Photo shows Silverado Contractors using a pick and lift to remove the connecting structure on the west wall of the Ace Gallery.



 UID:
 1158
 Latitude:
 34.066406

 Date:
 Nov 27, 2018
 Longitude:
 -118.398071

 Type:
 Construction Activity
 Elevation:
 --

Notes

Photo shows Silverado Contractors demolishing the southwest wall of the Ace Gallery.



 UID:
 1164
 Latitude:
 34.066813

 Date:
 Nov 28, 2018
 Longitude:
 -118.398208

 Type:
 Construction Activity
 Elevation:
 --

Notes

Photo shows crews water-proofing the west wall of the Ace Gallery.



 UID:
 1160
 Latitude:
 34.06645

 Date:
 Nov 28, 2018
 Longitude:
 -118.39793

 Type:
 Construction Activity
 Elevation:
 --

Notes

Photo shows crews processing debris in the Ace Gallery yard.



 UID:
 1159
 Latitude:
 34.066839

 Date:
 Nov 28, 2018
 Longitude:
 -118.398512

 Type:
 Construction Activity
 Elevation:
 --

Notes

Photo shows crews preparing to haul demolition debris off-site.







Photos



UID: 1162 Date: Nov 28, 2018 Type: Construction Activity Latitude: -118.398239 Longitude:

34.066272

34.066821

-118.398384

Elevation:

Notes

Photo shows crews processing debris in the Ace Gallery yard and preparing to haul debris off-site.



UID: 1163 Date: Nov 28, 2018 Type: Construction Activity

Longitude: Elevation: - - -

Latitude:

Notes

Photo shows crews processing debris in the Ace Gallery yard.



UID: 1165 Date: Nov 29, 2018 Type:

Latitude: 34.066879 Longitude: -118.398399

Elevation:

Notes

Photo shows an absence of construction activity in the Ace Gallery yard. Work for the day was cancelled due to rain.



UID: 1168 Nov 30, 2018 Date: Construction Activity Type:

Latitude: 34.066914 Longitude: -118.398415

Elevation:

Notes

Photo shows Silverado Contractors preparing to transport a man-lift off-site.



UID: 1166 Date: Nov 30, 2018 Construction Activity Type:

Latitude: 34.0664 Longitude: -118.398232

Elevation:



Notes

Photo shows Silverado Contractors moving demolition debris and removing the Ace Gallery foundation.



UID: 1167 Nov 30, 2018 Date: Construction Activity Type:

Latitude: 34.066879 Longitude: -118.3983

Elevation:

Photo shows Silverado Contractors processing demolition debris.







Attachment C – Construction Noise Monitoring Results

Receptor ID	Time of Measurement	Measured Noise Level Leq (15- Minute)	Applicable Noise Threshold	Exceeded Threshold?	Notes		
November 26, 2018							
					VAI loading scaffolding onto flatbed truck to demobilize. Silverado Contractors		
RD-8	8:43	65.7	71	No	excavator loading debris into bin.		
					TPOG water truck arriving on-site. Silverado Contractors excavator loading bin		
RD-5	9:15	63	68	No	and processing debris.		
RD-5	10:00	62.3	66	No	Silverado Contractors excavator sorting and processing debris.		
					Silverado Contractors skid steer with breaker attachment in operation, breaking		
					concrete along Compass building. Silverado Contractors excavator sorting and		
RD-5	10:30	66	66	No	processing debris.		
RD-5	10:46	66.2	66	Yes	Silverado Contractors skid steer with breaker attachment in operation, breaking concrete along Compass building. Silverado Contractors excavator sorting and processing debris.		
DD 5	11.40			V	Silverado Contractors skid steer with breaker attachment in operation, breaking concrete along Compass building. Silverado Contractors excavator sorting and processing debris. During reading, trash truck arrived in alley west of Reeves park, and collected trash bin, elevating noise levels from 11:43 to 11:45 hours. During reading, delivery truck for Sirtaj Hotel arrived at 11:55 hours, utilizing high volume back up alarm. This elevated noise levels. Re-read taken		
RD-5	11:40	66.9	66	Yes	immediately after end of current reading.		
					Silverado Contractors skid steer with breaker attachment utilized to break		
DD 5	11.57	66	66	Nie	concrete from connected wall section of Compass building. Silverado		
RD-5	11:57	66	66	No	Contractors excavator sorting and processing debris.		
					Silverado Contractors skid steer with breaker attachment utilized to break		
DD 5	12.12	65	65	Nie	concrete from connected wall section of Compass building. Silverado		
RD-5	12:13	65	65	No	Contractors excavator sorting and processing debris.		



Receptor ID	Time of Measurement	Measured Noise Level Leq (15- Minute)	Applicable Noise Threshold	Exceeded Threshold?	Notes
					Silverado Contractors skid steer with breaker attachment utilized to break
					concrete from connected wall section of Compass building. Silverado
RD-5	12:29	64.7	65	No	Contractors excavator sorting and processing debris.
					Silverado Contractors skid steer with breaker attachment utilized to break
					concrete from connected wall section of Compass building. Silverado
					Contractors excavator with breaker attachment utilized to break foundation of
RD-5	12:45	65	65	No	main structure of Ace Gallery.
					Silverado Contractors skid steer with breaker attachment utilized to break
					concrete from connected wall section of Compass building. Silverado
					Contractors excavator with breaker attachment utilized to break foundation of
RD-5	13:00	68	68	No	main structure of Ace Gallery.
					Silverado Contractors skid steer with breaker attachment utilized to break
					concrete from connected wall section of Compass building. Silverado
					Contractors excavator with breaker attachment utilized to break foundation of
RD-5	13:16	68	68	No	main structure of Ace Gallery.
					Silverado Contractors skid steer with breaker attachment utilized to break
					concrete from connected wall section of Compass building. Silverado
					Contractors excavator with breaker attachment utilized to break foundation of
RD-5	13:33	68	68	No	main structure of Ace Gallery.
					Silverado Contractors utilizing skid steer with breaker attachment to remove
					portion of western wall connected to Compass building. Excavator with breaker
					attachment utilized to break foundation of main building of Ace Gallery at the
RD-5	13:49	69	68	Yes	corner of S. Reeves and the alley south of the Ace Gallery.
					Silverado Contractors excavator with breaker attachment and skid steer with
					breaker attachment in operation. Skid steer and hand-held chipping gun used for
					demolition work on west wall attached to Compass building. Excavator working
RD-5	14:06	65.1	65	Yes	on demolition of foundation of Ace Gallery main building.
					Silverado Contractors excavator with breaker attachment and skid steer with
RD-5	14:23	66.3	65	Yes	breaker attachment in operation. Skid steer and hand-held chipping gun used for



Receptor ID	Time of Measurement	Measured Noise Level Leq (15- Minute)	Applicable Noise Threshold	Exceeded Threshold?	Notes
					demolition work on west wall attached to Compass building. Excavator working
					on demolition of foundation of Ace Gallery main building. Reading exceeded threshold by 1.3 LAeq (15 minute). Violation issued.
					Silverado Contractors excavator with breaker attachment and skid steer with
					breaker attachment in operation. Skid steer and hand-held chipping gun used for
					demolition work on west wall attached to Compass building. Excavator working
RD-5	14:39	64.1	65	No	on demolition of foundation of Ace Gallery main building.
22.5		- 4 -			Silverado Contractors excavator with breaker attachment. Excavator working on
RD-5	14:55	64.6	66	No	demolition of foundation of Ace Gallery main building.
					Silverado Contractors excavator with breaker attachment. Excavator working on
RD-5	15:11	66	66	No	demolition of foundation of Ace Gallery main building. Crew completing work
KD-3	13:11	00	00		for the day and closing for the end of the day. Tovember 27, 2018
RD-5	8:30	59.9	66	No	Moving debris with excavator and hand pulling pieces of west wall down.
RD-5	8:53	62	66	No	Moving debris with excavator and hammering. Moving debris with excavator and hammering.
RD-5	9:20	62.7	68	No	Loading haul truck with demolition debris.
KD-3	9.20	02.7	08	NO	Saw cutting into support beams on west wall of Ace Gallery and loading debris
RD-5	9:36	63.5	68	No	in haul truck.
RD-5	9:55	62.6	68	No	Saw cutting support beams and moving debris in Ace Gallery.
RD-5	10:21	61.8	66	No	Moving debris and saw cutting.
RD-5	10:40	65.1	66	No	Demolition; hammering foundation of Ace Gallery.
RD-5	11:00	64.7	66	No	Ace Gallery Demolition; excavator hammer breaking foundation.
RD-5	12:02	65.9	66	No	Loading demolition debris in haul truck.
RD-5	12:25	63.2	65	No	Moving debris and loading haul trucks.
RD-5	12:45	63.8	65	No	Moving Ace Gallery debris.
RD-5	13:15	63.8	68	No	Moving debris and digging.
					Moving debris and saw cutting support beams on southwest connecting wall of
RD-5	13:35	62.9	66	No	Ace Gallery.



Receptor ID	Time of Measurement	Measured Noise Level Leq (15- Minute)	Applicable Noise Threshold	Exceeded Threshold?	Notes
					Moving debris in Ace Gallery and taking down west wall. Exceedance was
RD-5	14:00	73.4	66	Yes	produced by a group of people talking near the sound meter.
RD-5	14:25	64.1	66	No	Moving debris and saw cutting steel support beams.
RD-5	14:47	64.6	65	No	Moving debris and sawing metal support beams.
RD-5	15:28	60.1	66	No	Removing wall systems support.
					Blow torching Ace Gallery west wall column support beams and pulling down
RD-5	15:48	61.5	66	No	wall.
				N	ovember 28, 2018
					Crews are processing the debris in the yard in preparation to be hauled out
RD-5	8:30	61.8	66	No	(starting at 9am).
RD-8	9:00	66.9	71	No	Crews are processing in the yard and loading debris into trucks.
					Crews are processing debris in the Ace Gallery yard, water-proofing the
RD-5	9:30	54.9	68	No	exposed west brick wall, and hauling demolition debris off-site.
					Crews are processing debris in the Ace Gallery yard, water-proofing the
RD-5	10:00	54.5	66	No	exposed west brick wall, and hauling demolition debris off-site.
					Crews are processing debris in the Ace Gallery yard, water-proofing the
RD-5	10:30	57.3	66	No	exposed west brick wall, and hauling demolition debris off-site.
					Crews are processing debris in the Ace Gallery yard, water-proofing the
RD-5	11:00	52.7	66	No	exposed west brick wall, and hauling demolition debris off-site.
					Crews are processing debris in the Ace Gallery yard, water-proofing the
RD-5	11:45	56.2	66	No	exposed west brick wall, and hauling demolition debris off-site.
					Crews are processing debris in the Ace Gallery yard, water-proofing the
RD-5	13:15	56.6	65	No	exposed west brick wall, and hauling demolition debris off-site.
					Crews are processing debris in the Ace Gallery yard, water-proofing the
RD-5	13:45	54.9	65	No	exposed west brick wall, and hauling demolition debris off-site.
					Crews are processing debris in the Ace Gallery yard, water-proofing the
RD-5	14:00	63.7	65	No	exposed west brick wall, and hauling demolition debris off-site.



Receptor ID	Time of Measurement	Measured Noise Level Leq (15- Minute)	Applicable Noise Threshold	Exceeded Threshold?	Notes
DD 0	14.20	60.0	70	N	Crews are processing debris in the Ace Gallery yard and water-proofing the
RD-8	14:30	69.9	70	No	exposed west brick wall.
RD-5	15:00	65.1	66	No	Crews are processing debris in the Ace Gallery yard and water-proofing the exposed west brick wall.
					Crews are processing debris in the Ace Gallery yard and water-proofing the
RD-5	15:30	65.2	66	No	exposed west brick wall.
RD-5	16:00	62.6	72	No	Crews are using the excavator to clean the debris in the yard.
November 30, 2018					
RD-5	8:12	57.8	66	No	Noise was limited to ambient.
RD-5	8:46	61.1	66	No	Crew was digging with the excavator.
RD-5	9:11	63.9	68	No	Crew was digging with excavator.
RD-5	9:40	63.7	68	No	Excavator removing foundation material.
RD-5	10:15	64	66	No	Excavator removing foundation material.
RD-5	10:45	63.6	66	No	Crew was processing demolition debris.
RD-5	11:15	59.4	66	No	Lunch break. Noise limited to ambient.
RD-5	12:02	64.6	65	No	Crew was breaking foundation with excavator.
					Crew was processing demolition material with excavator. Nearby leaf blower
RD-5	12:38	65.3	65	Yes	and garbage truck produced the noise exceedance.
RD-5	13:10	60.9	68	No	Crew was removing foundation and processing demolition material.
RD-5	13:39	61.9	68	No	Crew was processing demolition debris.
RD-5	14:12	62.3	65	No	Crew was processing demolition debris.
RD-5	14:36	63.7	65	No	Crew was processing demolition debris.
RD-5	15:00	61.5	66	No	Crew was excavating foundation of Ace Gallery.
RD-8	15:17	61.6	66	No	Crew was processing demolition debris.