

SERIAL NUMBER: 0213-007-007

UTM: 11-371460-3771660

CONTINUATION SHEET: Arden Drive Contractors Grouping

COMMON NAME: None

HISTORIC NAME: None

ADDRESS: 0512 Arden Drive North

PARCEL NUMBER: Unknown

CONSTRUCTION DATE: 1930

ORIGINAL OWNER: Unknown

ARCHITECT: Unknown

BUILDER: Unknown

DESCRIPTION:

Strict symmetry governs the appearance of this two story, American Colonial Revival house. Sheathed in dark shingles, the structure is capped by a side gable roof with a molded cornice. The entry is centered, flat-headed, and topped by an arched pediment of exaggerated proportions. Panelling characterizes both the door and the reveals. Panelled bases beneath the shuttered double-hung sash in the side bays of the three bay facade reiterate the motif. The second story also contains shuttered, double-hung sash, paired on the sides, single in the center. All of the windows are detailed with denticulated lintels. A broad brick chimney terminates the structure on the south.



CONTINUATION SHEET

Primary #

HRI #

Trinomial

NRHP Status Code: 5D3

Page 1 of 1 Resource Name or # 512 North Arden Dr.

☐ Continuation ☒ Update

P2. Location: 512 North Arden Dr.

B10 Significance:

This building appears in good condition with no significant alterations visible since the property was last evaluated in the 1985-1986 survey. It remains a contributor to a potential historic district defined as the Arden Drive Contractors Grouping that is eligible for local listing or designation..

P5b Description/Date of Photo: West elevation, looking southeast/May 2004



P8. Recorded by: Jan Ostashay, Peter Moruzzi, PCR Services, One Venture, Suite 150, Irvine, CA 92618

P9. Date Recorded: Tuesday, June 01, 2004