

SERIAL NUMBER: 0213-007-034

UTM: 11-371360-3772100

CONTINUATION SHEET: Arden Drive Contractors Grouping

COMMON NAME: None

HISTORIC NAME: None

ADDRESS: 0622 Arden Drive North

PARCEL NUMBER: 4341-005-011

CONSTRUCTION DATE: 2-17-30

ORIGINAL OWNER: Burgess; Carleton L.

ARCHITECT: McAlister; G.

BUILDER: Burgess; Carleton L.

DESCRIPTION:

Another example of the Spanish Colonial Revival style, this two story house is asymmetrical in plan. Its one and two story wings are sheathed in stucco and topped by tiled gable and hip roofs. The entry, located near the center of the facade, is arched and has a tiled intrados. Above it, a balcony has been enclosed, leaving the turned wood columns and supporting beams in place. Arched corbelling marks a second story overhang. Windows are casement in type; some are boxed by iron grilles. An archway spans the driveway at north end of the house to create a porte cochere. Other than the balcony, the house appears to be much as it was in a 1930 newspaper article.



## CONTINUATION SHEET

Primary #

HRI #

Trinomial

NRHP Status Code: 5D3

Page 1 of 1 Resource Name or # 622 North Arden Dr.

☐ Continuation ☒ Update

P2. Location: 622 North Arden Dr.

### B10 Significance:

*Since the property was last evaluated in the 1985-1986 survey, the balcony located above the entrance which previously had turned wood columns and supporting beams, has been removed. In its place, a round-arched window with flower box punctuates the exterior wall. Nonetheless, the building's massing, form, and overall condition suggest that the residence remains a contributor to a potential historic district defined as the Arden Drive Contractors Grouping that is eligible for local listing or designation.*

P5b Description/Date of Photo: West elevation, looking east/May 2004



P8. Recorded by: Jan Ostashay, Peter Moruzzi, PCR Services, One Venture, Suite 150, Irvine, CA 92618

P9. Date Recorded: Tuesday, June 01, 2004